




FE-04

Flat probes 23cm



Operating Instruction:

1. Blade Electrodes (2 pieces). Cable with Miniature 3,5 mm Jack-plug, 2 Laboratory plugs 4 mm. And 100 cm cable. Connect cable into the destined sockets at the measurement device and brushes.
2. Insert de Electrodes in the crack or crevasse.
3. Select the desired scale on your measuring device, f.e. Concrete Moisture.
4. Read out the measured value.
5. Dimension of Blade Electrode; Width 13 mm., Blade Length/Measuring depth 23 cm:
6. Accessory for i.e. VI-D4.