



# CAISSON

*Measuring equipment*

## SENSOR BE-03



### User manual

#### Operating Instruction:

1. Brush Electrodes (2 pieces). Cable with Miniature 3,5 mm Jack-plug, 2 Laboratory plugs 4 mm. And 100 cm cable. Connect cable into the destined sockets at the measurement device and brushes.
2. Insert de Electrodes in the drilled holes.
3. Select the desired scale on your measuring device, f.e. Concrete Moisture.
4. Read out the measured value.
5. Dimension of Brush Electrode; 7 mm. Diameter, 4 cm. Brush Length, 12 cm. Measuring depth.
6. Accessory for i.e. VI-D4.

---

**CAISSON Elektronik GmbH**  
Boschstrasse 16, D-47533 Kleve, Deutschland

tel: +49(0)2821-894390 [info@caisson-gmbh.de](mailto:info@caisson-gmbh.de) [www.caiisson-gmbh.de](http://www.caiisson-gmbh.de)